

## LIST OF U.S. CUSTOMS LABORATORY METHODS

USCL NUMBER	METHOD	TITLE
41-01	ASTM D 2810	<u>Test Method for pH of Leather</u>
41-02	ASTM D 2807	<u>Test Method for Chromic Oxide in Leather (Perchloric Acid Oxidation)</u>

# U.S. CUSTOMS LABORATORY METHODS

## USCL METHOD 41-01

Index

### ASTM D 2810 Test Method for pH of Leather

#### SAFETY PRECAUTIONS

*This method does not purport to address all of the safety problems, if any, associated with its use. It is the responsibility of the user of this method to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to its use.*

#### 1 SCOPE AND FIELD OF APPLICATION

This method covers the determination of the pH of all types of leather by measuring the pH of a distilled-water extract of leather. This method is to be used if applicable for commodities covered by Chapter 41 of the Harmonized Tariff Schedule of the United States (HTSUS).

#### 2 REFERENCES

*ASTM D 2810*  
Test Method for pH of Leather

# U.S. CUSTOMS LABORATORY METHODS

## USCL METHOD 41-02

Index

### **ASTM D 2807** **Test Method for Chromic Oxide in Leather** **(Perchloric Acid Oxidation)**

#### **SAFETY PRECAUTIONS**

*This method does not purport to address all of the safety problems, if any, associated with its use. It is the responsibility of the user of this method to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to its use.*

#### **1 SCOPE AND FIELD OF APPLICATION**

This method covers the determination of chromic oxide in leathers that have been partly or completely tanned with chromium compounds. It is specific for chromium in leather. The method is to be used as applicable in Chapter 41 of the Harmonized Tariff Schedule of the United States (HTSUS).

#### **2 REFERENCES**

##### ***ASTM D 2807***

Test Method for Chromic Oxide in Leather (Perchloric Acid Oxidation)